

Subject: Re: Westchester Town Center Irrigation System
From: Hector Banuelos <hector.banuelos@lacity.org>
Date: 06/27/2012 01:48 PM
To: Jruhlen916 <jruhlen916@aol.com>
CC: duckworth.donald@gmail.com

John,
UFD does not perform any work south of Manchester. Any work needed on the south medians including controller programming will need to be performed by the BID contractor.

Best Regards,

On Wed, Jun 27, 2012 at 1:35 PM, Jruhlen916 <jruhlen916@aol.com> wrote:
Hector,

It is SOUTH of Manchester Ave.

It is now 1:30 PM and I just drove by that area and there is no water funning on the street. But it s worth while taking a look at it.

John

-----Original Message-----

From: Hector Banuelos <hector.banuelos@lacity.org>
To: Jruhlen916 <jruhlen916@aol.com>
Cc: duckworth.donald <duckworth.donald@gmail.com>
Sent: Wed, Jun 27, 2012 1:27 pm

Subject: Re: Westchester Town Center Irrigation System

John/Donald,
8900 blk of Sepulveda is north of Manchester and UFD responsibility, but it appears the Ralphs is located south of Manchester.

BSS/UFD is not responsible for the irrigation systems on any of the medians south of Manchester.

Please confirm location.

Thanks

On Wed, Jun 27, 2012 at 11:17 AM, Jruhlen916 <jruhlen916@aol.com> wrote:

HECTOR,

I called Don last night about water running over the curb from the median across the street from the Ralph's grocery store south of Manchester. Water was running through the south bound traffic lanes.

John Ruhlen

-----Original Message-----

From: Hector Banuelos <hector.banuelos@lacity.org>
To: Donald Duckworth <duckworth.donald@gmail.com>
Cc: John Ruhlen <jruhlen916@aol.com>; Miki Payne2 <miki@hbdrollinger.com>
Sent: Wed, Jun 27, 2012 7:46 am
Subject: Re: Westchester Town Center Irrigation System

Hello Donald,
Are you referring to the median(s) on Sepulveda north or south of Manchester?

On Tue, Jun 26, 2012 at 7:39 PM, Donald Duckworth <duckworth.donald@gmail.com> wrote:

We are having a real problem with the new irrigation system in the medians at the Westchester Town Center. I think it is simply a lack of coordination between the City (or its contractor) and the Business Improvement District's contractor. The result is lack of water for our plant material, broken pipes, unnecessary call outs, and frustration. Can we meet with all of your affected supervisors and our BID representatives to resolve this ASAP?

Thanks Hector. (I understand you may not be the appropriate supervisor that we meet with but you are the only person other than Greg Monfette and Luis Torres that I've worked with on the maintenance side. I'm counting on your guidance to direct us properly.)

--

Hector M. Banuelos
Acting Street Tree Superintendent
Urban Forestry Division

Ph (213) 847-3077
Fax (213) 847-3033
hector.banuelos@lacity.org

Need a request?

Call Service Request (800) 996-2489 or contact bss.boss@lacity.org

--

Hector M. Banuelos
Acting Street Tree Superintendent
Urban Forestry Division

Ph (213) 847-3077
Fax (213) 847-3033
hector.banuelos@lacity.org

Need a request?

Call Service Request (800) 996-2489 or contact bss.boss@lacity.org

--

Hector M. Banuelos
Acting Street Tree Superintendent
Urban Forestry Division

Ph (213) 847-3077
Fax (213) 847-3033
hector.banuelos@lacity.org

Need a request?

Call Service Request (800) 996-2489 or contact bss.boss@lacity.org